

**N.C. DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF WASTE MANAGEMENT / SUPERFUND SECTION
INACTIVE HAZARDOUS SITES BRANCH**

TELEPHONE LOG

DATE: 08/11/08, 2:45 p.m.

SHEET: 1 OF 1

Call: Placed X , Received , Returned X

PROJECT: Mohawk-Karastan Plant	COUNTY: Pitt
CONVERSATION WITH: Jeff Camp	TELEPHONE: 252-551-2074
AFFILIATION: Greenville Utilities	
DISCUSSION:	
<p>I called Jeff to find out if he could give me any information about their site inspection. They conducted their usual yearly plant inspection for pretreatment. The only thing that concerned him was that the solvent tanks in front of the plant are not in good shape, though he has never seen a leak himself. The plant is supposedly going to install dikes around the tanks. The wastewater treatment lagoon, where they do pH adjustment, is stainless steel lined which Jeff thinks looks great. The lagoon was concrete lined before, though he never noticed anything bad about the concrete either. The lagoon was always filled with water though, so he has never seen the bottom. The plant did have a spill of solvent ~6-7 months ago. Only a small amount spilled and reportedly went into a storm drain. Jeff has been doing this for 15 years and says that Clarence Mills has always been cooperative. Clarence is very worried about this since they are trying to get ISO 14001 certification, which basically certifies that the plant is an environmentally friendly company. Jeff will fax me a copy of their completed inspection form. They also sent a copy of their findings to Kristin Jarman with Surface Water Protection in the Washington Regional Office.</p> <p>Kristin Jarman 252-948-3918</p>	

cc: WiRO - IHSB Files **Filed By:** Ginny Henderson